Pneumatic // -0.3...4 bar





Your advantages		
Турее	P4	
	 Testing, adjustment and calibration of all types of pressure gauges Long-term stable measurements without pressure loss due to hermetically sealable vacuum chamber Precise adjustment in the mbar range thanks to ultra-fine thread pitch and large volume control valve Tool-free change between overpressure and vacuum generation Smallest mobile hand test pump on the market 	

Technical data			
Typee	P4		
Pressure ranges			
→ Negative pressure	-0.3 bar (depending on test sample/reference)		
→ Positive pressure	4 bar		
Pressure medium	Air		
Connections			
Reference pressure gauge	G1/4 female thread with PA hose (2 x 1 m)		
Test sample	G¼ with quick coupling and pressure hose (1 m)		
Basic			
Dimensions	Approx. 225 x Ø 55 mm		
Weight	Approx. 980 g		
Solid			
Dimensions (case)	Approx. 450 x 370 x 110 mm		
Weight	Approx. 4.2 kg		
+ Adapter kit	Chrome-plated brass, G1/8, G1/4, G3/8, G1/2, 1/8 NPT, 1/4 NPT, 1/2 NPT, M12 x 1.5, M20 x 1.5, G1/8, G1/4		
+ Seal kit	PA flat gaskets and O-rings		

Order code			
Туре	Version	Order nummer	
P4	Basic	EPPM004EBL0000	
	Solid (incl. case and adapter)	EPPM0040BL0000	